

BP.0161/138

1 June 2018

**-Translation-**

Subject: Temporary problem with transmission line system

To: President of the Stock Exchange of Thailand

Banpu Public Company Limited ('Banpu') would like to inform the Stock Exchange of Thailand that its subsidiary Banpu Power Public Company Limited ("BPP") had been notified by Hongsa Power Company Limited that at 13:06 hrs. There was lightning on 500 kV transmission line located 14 kilometers from Hongsa Power plant. The transmission and substation protection system activated, therefore transmission system was temporarily disconnected from the power plant. The system resumed normal operation at 14:47 hrs.

Please be informed accordingly and kindly disseminate the information herein to investors.

Sincerely yours,

**-signature-**

(Mrs. Somruedee Chaimongkol)

Chief Executive Officer